RECESSED HAND DRIER


Specifications and Dimensions


Model	Volts	Watts	Amps	Housing Dimensions: mm (in)		
				W	Н	D
2200SA(R)	110-120Vac 220-240Vac	1848-2200W 1848-2200W	16.8-18.3A 8.4-9.2A	340mm(13-25/64")	361mm(14-7/32")	156mm(6-9/64")

Recessed Box Diagrams:

Rough wall opening: 325*347*158 mm (12-51/64*13-21/32*6-7/32 in).











Installation:

1. Remove the front plate from the




Rough wall opening: 325*347*158 mm (12-51/64*13-21/32*6-7/32 in)

2. Remove the main unit from the recessed box.




3. Insert the bushing into the side hole of the recessed box. Insert the recessed box into the wall and fixe it. Bushing


6. Attach the front plate back to the recessed box.



5. The wire connections are as follows:



4. Attach the main unit back to the recessed box.



Connections:

- A. Connect the live wire (colored red or brown) to the terminal block marked "L".
- B. Connect the neutral wire (colored black or blue) to the terminal block marked "N".
- C. Connect the ground wire (colored green and yellow) to the green screw marked "...".

